

Addendum IV
Invitation to Bid for Tank Inspection Services
ITB No. 20-0818-03
August 31, 2020

Attention of all bidders is directed to the following clarifications made to ITB No. 20-0818-03; Water Tank Inspection Services:

1. The Scope of work consist of six (6) service tanks and one (1) out of service tank.
2. The out of service tank is identified in the chart below, as the Peyton Standpipe Tank, located at 802 Peyton Road, Horizon City, 79928. The Payton Standpipe Tank is to be inspected for structural and footing purposes. It is used for communication purposes. The Payton Standpipe Tank is categorized as a standpipe and is not an elevated tank.
3. All seven (7) tanks are to be inspected for structural integrity and footings.
4. The chart below identifies all tanks and provides their address, capacity, style, type and service/out of service status.

Tank Name	Tank Address	Capacity	Style	Type	IN/OUT Service
Mitchell Tank #1	1150 Mitchell Drive	2 MG	GST	Ground Storage Tank	In-Service
Mitchell Tank #2	1150 Mitchell Drive	2 MG	GST	Ground Storage Tank	In-Service
Sand Hills Tank #2	1150 Mitchell Drive	350K	GST	Ground Storage Tank	In-Service
Sand Hills Tank #1	15900 Alzada Avenue	350K	GST	Ground Storage Tank	In-Service
Eastlake Tank	11080 Gateway East	2MG	GST	Ground Storage Tank	In-Service
Fordham Elevated	13142 Fordham	200K	EST	Elevated Tank	In-Service
Peyton Standpipe Tank	802 Peyton Rd, Horizon City	25K	Standpipe	Standpipe Decommissioned	Out-Service

Please acknowledge receipt of all Addendums as part of bid documentation submittals. Not doing so may result in a disqualification of your bid.

END OF ADDENDUM IV